

The background of the entire page is a dark gray topographic map with white contour lines. The lines are irregular and wavy, representing elevation changes across a terrain.

GEOTERRA

DOMINICANA

ANÁLISIS DE LAS ARCILLAS



Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **GeoTerra Dominicana, SRL.**
Autopista Duarte No.41
Santo Domingo

Submitted By: GeoTerra Dominicana, SRL.
Receiving Lab: Dominican Republic - Maimon
Received: October 12, 2011
Report Date: October 28, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS

DRG11000401.1

CLIENT JOB INFORMATION

Project: LA_MAJAGUA
Shipment ID:
P.O. Number: SIN_REFERENCIA
Number of Samples: 1

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
4X	1	Li2B4O7/LiBO2 fusion, analysis by XRF		Completed	VAN
2A Leco	1	Analysis by Leco	0.1	Completed	VAN

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

ADDITIONAL COMMENTS

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

Invoice To: **GeoTerra Dominicana, SRL.**
Autopista Duarte No.41
Santo Domingo

CC: Ricardo Baez Diaz



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only. All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted. *** asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.



Acme Analytical Laboratories (Vancouver) Ltd.
 1020 Cordova St. East Vancouver BC V6A 4A3 Canada
 Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **GeoTerra Dominicana, SRL.**
 Autopista Duarte No.41
 Santo Domingo

Project: LA_MAJAGUA
 Report Date: October 28, 2011

Page: 2 of 2 Part 1

CERTIFICATE OF ANALYSIS

DRG11000401.1

Method	WGHT	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X 2A	Leco 2A	Leco
Analyte	Wgt	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	MnO	TiO2	P2O5	Cr2O3	Ba	LOI	SUM	TOT/C	TOT/S	
Unit	kg	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	
MDL	0.01	0.1	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.001	0.01	-5.11	0.01	0.02	0.02	
LM_PR-06	Clay	50.6	30.85	3.02	0.28	0.58	1.18	1.94	0.10	0.30	0.01	0.008	0.08	11.54	100.5	0.09	<0.02	



Acme Analytical Laboratories (Vancouver) Ltd.
 1020 Cordova St. East Vancouver BC V6A 4A3 Canada
 Phone (604) 253-3158 Fax (604) 253-1716

www.acmelab.com

Client: **GeoTerra Dominicana, SRL.**
 Autopista Duarte No.41
 Santo Domingo

Project: LA_MAJAGUA
 Report Date: October 28, 2011


Page: 1 of 1 Part 1

QUALITY CONTROL REPORT


DRG11000401.1

Method	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X 2A	Leco 2A	Leco
Analyte	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	MnO	TiO2	P2O5	Cr2O3	Ba	LOI	SUM	TOT/C	TOT/S	
Unit	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	
MDL	0.1	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.001	0.01	-5.11	0.01	0.02	0.02	
Reference Materials																	
STD CSC	Standard															3.08	4.18
STD OREAS76A	Standard															0.18	18.03
STD SO-18	Standard	58.8	14.08	7.68	6.42	3.40	3.74	2.16	0.41	0.71	0.82	0.590	0.06	1.90	101.0		
STD SY-4(D)	Standard	50.0	20.74	6.22	8.06	0.52	7.07	1.60	0.11	0.28	0.13	<0.001	0.04	4.56	99.56		
STD CSC Expected																2.94	4.25
STD OREAS76A Expected																0.16	18
STD SY-4(D) Expected		49.9	20.69	6.21	8.05	0.54	7.1	1.66	0.108	0.287	0.131		0.034	4.56			
STD SO-18 Expected		58.47		7.67	6.42	3.35	3.71	2.17	0.39	0.69	0.83		0.0514				
BLK	Blank															<0.02	<0.02
BLK	Blank	<0.1	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.001	<0.01	0.00	<0.01		

GEO TERRA DOMINICANA

 +1 (809) 369 8984

 Autopista Duarte
No.41 Santo Domingo

 info@geoterradominicana.com
www.geoterradominicana.com